



# John Deere Gator Windshield “TS, TX, TH, TE Series”

Part# FAA-DCGT-W

(Part# FAS-DCGT Sunshade Required for Windshield Installation)

## Assembly Instructions




TRACTOR SUNSHADE  
6010 N 53rd Dr  
Glendale AZ, 85301

Phone: 623-934-9340 Email: [info@tractorsunshade.com](mailto:info@tractorsunshade.com) Website: [tractorsunshade.com](http://tractorsunshade.com)

## Part# FAA-DCGT-W Components

- Windshield (Hardware Applied)
- Cowl (Hardware Applied)

Please preview all 3 steps prior to assembly



### Step 1: Attach Cowl.

First, remove all pre-attached hardware from the COWL. Position COWL (finished side forward) on the Gator's hood, mark through the 1/4" holes in the lower corners, left and right. Set aside the COWL and drill four 1/4" holes through the Gator's plastic fenders. Re-apply the COWL, attach to Gator using the pre-attached hardware (2 bolts per side) that were removed earlier.



### Step 2: Attach Windshield.

Carefully remove the protective paper on both sides of the windshield. Next, using the bolts that attach the sunshade to the tubes, loosely attach the windshield mounting strip to the bottom of the tubes. Do not tighten bolts until you have completed Step 3



### Step 3: Attach Windshield To Cowl.

Gently pull down on the windshield on both sides until you can insert the three pre-attached bolts from the front. Make sure you have the rubber-backed washers on the front side of the windshield and the rubber spacers in the correct position. Attach the plain washers followed by the Nylock nuts, and gently tighten until the rubber spacers slightly "bulge".



